

Tri-State Wastewater
103 Thrush Rd.
Warwick, RI 02886

January 2015 Monthly Pump Station Report.
As of February 1st 2015
Mill Street.

Pump station is in good operating condition.

- Recommend Generator P.M. (Filters ordered).
- Battery replacement recommended (no date).
- Locks ordered (keyed alike).

Schooner Drive.

Pump station is in good operating condition with the exceptions of:

- Cabinet heater needs replacing. (Quote sent).
- Transformer needs replacing. (Quote sent).
- Generator P.M. (Completed).
- Battery replacement recommended (no date).
- Locks ordered (keyed alike) small locks changed waiting on larger locks.

Hurst Lane.

Pump station is in good operating condition with the exceptions of:

- Radiator and Hoses replaced.
- Generator P.M. (Completed).
- Battery replacement recommended (no date).
- Float switch J-box in wet well need mounting.
- Valve pit was pumped due to sump not working and high level (will send quote to replace).
- Wet well was cleaned (grease & solids).
- Locks ordered (keyed alike) small locks changed waiting on larger locks.

Tri-State Wastewater
103 Thrush Rd.
Warwick, RI 02886

Blackbird Court.

Pump station is in good operating condition.

-Locks changed (keyed alike).

-Generator P.M. (completed).

-Replacement of battery recommend (no date).

Industrial Way.

Pump station is in good operating condition with the exceptions of:

-Pump #2 out for evaluation (due to short in windings). Waiting on pricing for alternative pump brand to help reduce replacement cost.

-Float switch J-box in wet well need mounting.

-Generator P.M. (Completed).

-Battery replacement recommended (no date).

-Cleaned Wet well (grease & solids).

-Locks ordered (keyed alike) small locks changed waiting on larger locks.